

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
MSS,  
2-CORI,  
11-

O. R. Smith House  
Corinth  
Alcorn County  
MS

HABS No. MS-231

Jack E. Boucher, Photographer

March 1975

MS-231-1	NORTH FRONT, ONE AND ONE HALF-STORY PORTICO
MS-231-2	NORTH FRONT AND EAST SIDE
MS-231-3	INTERIOR, FIRST FLOOR, STAIRRAIL, NEWELL, PANELLING, WAINSCOT
MS-231-4	INTERIOR, FIRST FLOOR, FIREPLACE, WOOD PANELLING SURROUNDS PLAIN STONE TRIM